

<b>REPORT OF ANNUAL INSPECTION OF CCR LANDFILL</b>	
<b>CCR LANDFILL NAME:</b> Red Hills Generation Facility Ash Management Unit	
<b>OWNER OF CCR LANDFILL:</b> Choctaw Generation Limited Partnership, LLLP	
<b>INSPECTION DATE:</b> August 30, 2018	
<b>INSPECTING ENGINEER:</b> Jacob A. Jordan, PE MS PE 27315	
<b>APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT THE TIME OF INSPECTION (CU. YDS.)</b>	<b>5,350,645</b>
<b>ANY CHANGES IN GEOMETRY OF THE CCR UNIT SINCE THE PREVIOUS ANNUAL INSPECTION?</b>	<b>NO</b>
<b>(IF YES, DESCRIBE):</b>	
<b>ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, OR ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT OR APPURTENANT STRUCTURES?</b>	<b>NO</b>
<b>(IF YES, DESCRIBE):</b>	
<b>ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION?</b>	<b>NO</b>
<b>(IF YES, DESCRIBE):</b>	
<b>WERE ALL CORRECTIVE ACTIONS IDENTIFIED DURING THE PREVIOUS ANNUAL INSPECTION COMPLETED?</b>	<b>NO</b>
<b>(IF NO, DESCRIBE):</b> Additional measures for run-off controls need to be implemented	