

REPORT OF ANNUAL INSPECTION OF CCR LANDFILL	
CCR LANDFILL NAME: Red Hills Generation Facility Ash Management Unit	
OWNER OF CCR LANDFILL: Choctaw Generation Limited Partnership, LLLP	
INSPECTION DATE: September 28, 2016	
INSPECTING ENGINEER: Jason S. Wilson, PE MS PE 27022	
APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT THE TIME OF INSPECTION (CU. YDS.)	5,323,468*
ANY CHANGES IN GEOMETRY OF THE CCR UNIT SINCE THE PREVIOUS ANNUAL INSPECTION?	NO
(IF YES, DESCRIBE):	
ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, OR ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT OR APPURTENANT STRUCTURES?	NO
(IF YES, DESCRIBE):	
ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION?	NO
(IF YES, DESCRIBE):	
WERE ALL CORRECTIVE ACTIONS IDENTIFIED DURING THE PREVIOUS ANNUAL INSPECTION COMPLETED?	N/A
(IF NO, DESCRIBE):	
*Inspection dated December 8, 2015 reported 8,004,589 cubic yards of ash at the time of inspection. This number was later revised to 5,292,267 cubic yards based on updated survey information.	